### Today's protagonist is Ivan




# Setup-1



## Setup-2











#### Material Stock-1



#### Material Stock-2



#### Cut material



## **Drilling Room**



## Before drilling



## Drilling



## After drilling




#### **Before Electroless**



#### Electroless-1



#### Electroless-2




## Grinding machine



### Drill Film/Wet Film-1



### Drill Film/Wet Film-2



#### Circuit Film-1



#### Circuit Film-2



## Exposure machine-1




### Exposure machine-2




#### Handsome man



### Exposure-1




### **Before Develop**



## Develop machine



## After Develop



# Plating line




### Plating copper



## Plating Tin












## Take off the Dry film



## **Before ETCH**



## Etch line



### Etch-1



## Etch-2



### Take off the Tin



#### Print Solder mask



## Ink




## Solder Exposure



#### Film room




## Solder Develop



## Solder mask develop











## Print overlay-1



## Print overlay-2



#### Oven



## HASL/ENIG

HASL/ENIG


## Routing-1



## Routing-2



### V-groove



## FP-testing



## Fixture testing-1



### Fixture testing-2



# FQC



### Pack-1



### Pack-2



### Parcel-1



### Parcel-2



### Parcel-3

